











Arc start、feedback (Original)Arc voltage

16

4 core cable 1.5m²




17


4 core cable 1.5m²



18




Quick Fix Connector Quick Fix Connector




Driver CN3





Motor side




HYD-MC400
Drive1



J8
DB15female
plug



X axis CN1



Cable model:4x0.3mm^2
Twisted pair shield

CNC X-axis drive cable

CB00W1

